

Building Committee Report
June 21, 2004

I met with a representative of the Lexington County Fire Department in order to create a floor plan and locate the utilities (gas, water, & electricity entry points and cut off) of St. Albans for their records. They noted several things that would not pass should a fire inspector visit St. Albans. They are listed below:

1. Fire extinguishers needed to be inspected and recharged if necessary (ours were 8 years past due).
2. St. Albans needs to have a street number sign that is visible from the street.
3. Exit signs in need of bulbs.

We have had the extinguishers inspected by Caraway Co. They recommend that we install an improved fire deterrent system over the stove in order to meet current codes. I will look into this and items 2 & 3 in July.

Lewis Brunson